

## **SAFETY RECALL NOTICE**

### **HONDA LAWN MOWER**

#### **MODEL: HRU196M2 & HRU216M3**

#### **CARBURETTOR FUEL LEAK FROM NEW**



Frame Number Locations

#### **What is the reason for this notice?**

Honda Motor Co., Ltd, is conducting a Safety Recall Campaign of specific Honda HRU series Lawn Mowers sold between 10th September 2018 and 4th March 2019.

#### **What is the problem?**

Power & Marine Ltd is conducting a RECALL of certain HRU - Lawn Mower due to a potential fuel leak from the Float Chamber on the carburettor. Honda Motor Co., Ltd has determined that due to misalignment of the float chamber during fuel removal on the production line. The float chamber may not have been installed correctly on the carburettor body and can cause the fuel to leak during operation, storage or transportation and in the worst case, could cause a FIRE, although there have been no reported cases to date.

#### **Affected units?**

A list of affected units is available. Scroll down to page 2 for a list of affected Frame Numbers.

#### **What should you do?**

Call any authorised Honda Power Products dealer and make an appointment to have the Float Chamber on the carburettor inspected and replaced if necessary. Your Honda dealer can inform you of the length of time required to complete this repair. The dealer will inspect and if required replace the affected components at no cost to you. If you need assistance locating a servicing Dealer, please visit our website [www.hondapowerequipment.co.nz](http://www.hondapowerequipment.co.nz) and select "Find a Dealer".

#### **If you have any questions?**

Should you have any questions or concerns regarding this notice that your Honda authorised servicing dealer cannot answer please contact our Honda Power Equipment Service Department on 09 571-1140 or alternatively you can email us at: [service.department@powermarine.co.nz](mailto:service.department@powermarine.co.nz)

If you have on sold your Honda Lawn mower, please advise us of the details of the new owner, as we would like to make contact with the new owner and advise him/her of this Safety Recall Campaign.

It is our goal to provide you with the highest quality product and best after sale service. We apologise in advance for any inconvenience this situation may cause.

We thank you for your purchase of our Honda product and your cooperation.

**Power & Marine Limited**

**HRU196M2**

#	Model	Type Code	Frame Number
1	HRU196M2	PWUH	MAYU-2000021
2			MAYU-2000022
3			MAYU-2000023
4			MAYU-2000024
5			MAYU-2000065
6			MAYU-2000066
7			MAYU-2000067
8			MAYU-2000069
9			MAYU-2000070
10			MAYU-2000071
11			MAYU-2000072
12			MAYU-2000287
<b>HRU196M2</b>		<b>Total units:</b>	<b>12</b>

**HRU216M3**

#	Model	Type Code	Frame Number
1	HRU216M3	TBUH	MATU-3000009
2			MATU-3000010
3			MATU-3000011
4			MATU-3000013
5			MATU-3000014
6			MATU-3000418
7			MATU-3000419
8			MATU-3000420
9			MATU-3000421
10			MATU-3000422
11			MATU-3000423
12			MATU-3000424
13			MATU-3000549
14			MATU-3000550
15			MATU-3000551
16			MATU-3000552
17			MATU-3000569
18			MATU-3000571
19			MATU-3000573
20			MATU-3000574
21			MATU-3000575
22			MATU-3000576
23			MATU-3000593
24			MATU-3000594
25			MATU-3000595
26			MATU-3000597
27			MATU-3000598
28			MATU-3000599
29			MATU-3000600
30			MATU-3000605
31			MATU-3000606
32			MATU-3000607

33	<b>HRU216M3</b>	<b>TBUH</b>	MATU-3000608		
34			MATU-3000609		
35			MATU-3000610		
36			MATU-3000611		
37			MATU-3000612		
38			MATU-3000629		
39			MATU-3000630		
40			MATU-3000631		
41			MATU-3000632		
42			MATU-3000634		
43			MATU-3000637		
44			MATU-3000639		
45			MATU-3000640		
46			MATU-3000821		
47			MATU-3000822		
48			MATU-3000823		
49			MATU-3000829		
50			MATU-3000830		
51			MATU-3000831		
52			MATU-3000993		
53			MATU-3000994		
54			MATU-3000995		
55			MATU-3000996		
56			MATU-3001000		
57			MATU-3001001		
58			MATU-3001002		
59			<b>HRU216M3</b>	<b>TBUH</b>	MATU-3001005
60					MATU-3001008
61	MATU-3001011				
62	MATU-3001012				
63	MATU-3001013				
64	MATU-3001014				
65	MATU-3001015				
66	MATU-3001019				
67	MATU-3001020				
68	MATU-3001021				
69	MATU-3001022				
70	MATU-3001023				
71	MATU-3001025				
72	MATU-3001026				
73	MATU-3001031				
74	MATU-3001032				
75	MATU-3001035				
76	MATU-3001036				
77	MATU-3001039				
78	MATU-3001040				
<b>HRU216M3</b>			<b>Total units: 78</b>		